


- Traitement anti-corrosion + remise en peinture
- Réfection des couvertines en zinc quartz
- ▢ Remplacement / complément



Architectural elevation drawing of a building facade. The drawing includes various annotations and level markers:

- Level Markers (NGF):**
 - NGF:191.07 (Top right)
 - NGF:190.30/N2 (Top right)
 - NGF:188.80 (Top right)
 - NGF:185.25/N1 (Middle right)
 - NGF:180.25/N0 (Bottom right)
 - NGF:179.80/TN (Bottom right)
 - NGF:179.40/TN (Bottom left)
 - NGF:178.63/TN (Bottom right)
- Window Annotations:**
 - FN 1.13 (Top row, second from left)
 - FN 1.14 (Top row, third from left)
 - FN 1.15 (Top row, fourth from left)
 - FN 1.16 (Top row, fifth from left)
 - FN 1.17 (Top row, sixth from left)
 - FN 1.18 (Top row, seventh from left)
 - FN 0.9 (Bottom row, first from left)
 - FN 0.10 (Bottom row, second from left)
 - FN 0.11 (Bottom row, third from left)
 - FN 0.12 (Bottom row, fourth from left)
 - FN 0.13 (Bottom row, fifth from left)
 - FN 0.14 (Bottom row, sixth from left)
- Door Annotation:**
 - PN 0.15 (Bottom row, seventh from left)
- Other Annotations:**
 - SN-1.1' (Bottom row, first from left)
 - SN-1.2' (Bottom row, second from left)
 - IS 1UP (Bottom right)
 - FACADE ACCESSIBLE - VOIE ENGIN (Bottom center)